




## HZFA-V








AC220V  $\pm 20$

15A





CT/PT

PT

CT

PT

/





2000


/

RS232

U

20Kg

|    |      |         |      |        |
|----|------|---------|------|--------|
| CT | 220V | 0—1000V | 3KVA | < 0.5% |
| PT | 220V | 0—330V  | 3KVA | < 0.5% |
| CT | 220V | 0-8V    |      | < 0.5% |
| PT | 220V | 0—1000V |      | < 0.5% |
| CT |      |         |      |        |





220V

CT      PT      U

全功能互感器综合测试仪

CT 测试

PT 测试

数据查询

U盘转存

系统设置

08-12-28 15:30

CT

CT

CT

A.

CT 参数设置

编号: ABC001

相序: A


Kn: 1

变比: 1000:5



确定

:

CT










d.



( )







CT

b.

CT

L1 L2

CT

K1 K2

c.




CT




e.

5

200A





E.



4. PT

PT



PT

PT

CT


CT

A. PT



PT

PT





a.




0 - 3 A



0~330V




b.



B. PT

PT

PT



| PT 变比测试         |      |
|-----------------|------|
|                 | 自动试验 |
| 一次输出电压<br>1000V |      |
| 返回上层            |      |

a.



0 - 1000





5

b.





| 一次电压: 1000 V |       |
|--------------|-------|
| 角差           | 1.83° |
| 比差           | 0.00% |
| 返回上层         |       |



















“

”

“

”

1

2

1.

2.



1

2

3

2

24

027-83267669

24

48

4

225

027-83267669

[www.whhezi.com](http://www.whhezi.com)

whhezi@163.com